


SHAD

HONDA XL 750 TRANSALP '23 TOP MASTER H0TR73ST

BCN



1 263282 x1



2 260740 x4
Ø20 Ø11 x 11



3 303045 x6
Ø8



4 304169 x2
M8x50 DIN 7380



5 302024 x4
M8



6 304032 x2
M8x50 DIN 7991

WARNING!


GB Do not fully tighten the screws until it is ensured that the KIT is correctly attached and aligned. Check tightness every 4 months.

E No apretar los tornillos del todo hasta asegurarse que el KIT está correctamente colocado y alineado. Repasar apriete cada 4 meses.

D Ziehen Sie die Schrauben nicht ganz fest, bevor Sie sich nicht vergewissert haben, daß der Bausatz korrekt eingestellt und ausgerichtet ist. Alle 4 Monate Drehmoment überprüfen.

I Non stringere del tutto le viti fin tanto non si è sicuri che il kit è collocato correttamente e allineato. Controllare il serraggio delle viti ogni 4 mesi.

F Ne pas serrer les vis avant d'être sûr que le KIT soit correctement positionné et ajusté. Vérifier le serrage des vis tous les 4 mois.



WWW.SHAD.ES

REF. 500479 Edition 2ª

IMPORTANT: Based on European models. For compatibility with models in other continents, check www.shad.es